

CAPuS PROJECT – Causes of Damage, agents and deterioration processes (WALL PAINTING)

UVIGO TEAM

APRIL 2019

1. GENERAL DATA			
NUMBER OF PARTNER:	P15		
TYPE OF WORK:	MURAL PAINTING		
COUNTRY:	SPAIN		
CITY:	VIGO		
ADDRESS:	RUA DOUTOR CARLOS COLMEIRO LAFORET		
OWNER / CUSTODIAN:	UNKNOWN		
LEGAL PROTECTION:	INEXISTENT		
ARTIST:	LIQEN		
TITLE OF THE WORK:	ENTARAÑA		
YEAR OF EXECUTION:	2008		
MATERIALS:	Acrylic and spray paints on reinforced concrete and brick wall plastered with cement mortar		
DIMENSIONS (cm):	Hight: 300	Width:900	Depth:70

2. DESCRIPTION OF THE PROBLEM (DEGRADATION)

PRIMARY CAUSES (RELATED TO THE TECHNIQUE, TECHNOLOGY AND LOCATION OF THE OBJECT)


FACTORS RELATED TO THE CONSTRUCTION BASE		
	CONCRETE	The materials used for concrete manufacturing are of poor quality. So, concrete has a weak resistance.
	CEMENT	
	BRICK	
	REINFORCED CONCRETE	
	WOOD	
	METAL	
	OTHER	
MATERIALS USED FOR COATING, PLASTER		
	BINDER	
	FILLER	
MATERIALS USED TO MAKE POLICHROMY (PAINTING MATERIALS)		
	BINDER	
	PIGMENT	
MATERIAL USED TO PROTECT THE SURFACE		
LOCATION OF AN OBJECT IN A PLACE NEGATIVELY AFFECTING ITS LASTING		
	SETTING OF FOUNDATIONS	
	UNSTABLE SUPPORT	
	FOUNDATIONS AND NONE FOUNDATIONS	
	TYPE OF GROUND	
	TECTONIC MOVES	
	VIBRATIONS, SHAKES	

	SOIL DAMP	
<u>LATER INTERFERENCES</u>		
	REPARATIONS	
	RENOVATION OF A BUILDING	
	SETTING UP A NEW INSTALLATIONS	
	REPAINTING	
	LATER CONSERVATIONS-RESTAURATIONS	
	VANDALISM	
<u>THERMAL-HUMIDITY FACTORS</u>		
	CAPILLARY MOISTURE	YES
	MOISTURE CONDENSATION	
	WATER INFILTRATION FROM RAINFALLS, SNOW FALLS AND/OR BUILDING INTALATIONS	YES (RAIN INFILTRATIONS)
	SORPTION MOISTURE	
	BUILDING CONSTRUCIONAL MOISTURE	
<u>THERMAL FACTORS</u>		
	TEMPERATURE FLUCTUATIONS (DAILY, SEASONAL, ANNUAL)	
	GEOGRAPHIC LOCATION OF THE OBJECT (N, S, E, W)	
	SEASONAL FROST PENETRATION	
	EXPOSITION ON LIGHT	
	HIGH TEMPERATURE INFLUENCE	
<u>PHYSICO-CHEMICAL FACTORS</u>		
	AIR POLLUTION	

	SALT IN THE AIR	
	SALT DISSOLUTION AND CRYSTALIZATION	
	CORROSION	
<u>BIOLOGICAL FACTORS (biological colonisation, biofilm)</u>		
	ANIMAL ACTIVITIES	
	MICROORGANISMS	
	FUNGUS	Evidences of MICROSCOPIC FUNGI colonization, both over and under the paint layer. Analytical confirmation needed.
	MOLDS	
	ALGAE	
	MOSS (lichens)	LICHENIC colonization, both over and under the paint layer. MOSS growth under the paintng layers
	PLANTS (SHRUBS, TREES)	Vascular plants growing near the floor on concrete hollows
<u>MECHANICAL FACTORS</u>		
	MECHANICAL INJURIES	YES
	ABRASIONS	YES, of anthropic origin
	PUBLIC ACCESS, ATTENDANCE OF THE LARGE GROUPS OF HUMANS	YES
	INDUSTRIALIZATION	
<u>OTHERS</u>		
It seems that the wall was not clean before painting. Therefore, paint layer was applied on a concrete support previously colonized by microscopic fungi and lichens. This fact decreases the durability of the paint layer and its conservation.		



PLACE TO INSERT THE PHOTO TO MARK THE DETAILS OF THE STATE OF PRESERVATION OF THE OBJECT ON IT



BIOLOGICAL ALTERATION	Biological colonization	
OPTICAL ALTERATION	Fading	
LOSS OF MATERIAL-paint	Peeling	
	Loss	
	Craquelure	
LOSS OF COHESION-paint and substrate	Flaking	
	Fissuring	
ADDITION OF SUBSTANCES	Vandalic graffiti	

This document was produced within the project ***Conservation of Art in Public Spaces (CAPuS)***.

Authors:

Teresa Rivas Brea, Enrique Alonso Villar, Santiago Pozo
Antonio- UNIVERSIDADE DE VIGO (SPAIN)



Education, Audiovisual and
Culture Executive Agency
Erasmus+: Higher Education-Knowledge
Alliances, Bologna Support, Jean Monnet

CAPuS project has received funding from the
European Commission, Programme Erasmus+
Knowledge Alliances 2017, Project N°
588082-EPP-A-2017-1-IT-EPPKA2-KA

The European Commission's support for the production of this publication does not constitute an endorsement of the contents, which reflect the views only of the authors, and the Commission cannot be held responsible for any use which may be made of the information contained therein.